

SO MANY DUMB WAYS TO DIE: THE LASER ENGRAVER TROUBLE-SHOOTING ROAD TO NOWHERE

THERE ARE A DOZEN WAYS THE LASER CAN FAIL, SO IT OFTEN WILL. WHEN THE LASER FAILS TO FIRE, FOLLOW THE FLOW CHART TO DIAGNOSE AND CORRECT THE POINT OF FAILURE. SOME FAILURE POINTS ARE QUICK AND EASY TO FIND... OTHERS REQUIRE SPECIALIST KNOWLEDGE. STILL OTHERS MUST CONSULT THE ILLUMINATI.

LIGHT COLORS = CLIENT CAN DIAGNOSE
MEDIUM COLORS = MONITOR ON DUTY MUST DIAGNOSE
DARK COLOR = CALL IN THE COORDINATOR!

CHANCE OF CAUSE

